THE PROBLEM

TIMBER DOOR FAILURES:

- X Swelling/de-lamination from moisture
- Breaks-down with heavy usage
- X Non-compliant installation/repair
- Disposed of at end of project
- Closer 'popping'
- Short life-span

THE SOLUTION

NEXT GENERATION FIRE PROTECTION

Tempus

TEMPORARY FIRE DOORS

E60 FIRE RATED
MAINTENANCE FREE
ASSURED COMPLIANCE


UNLATCHED

DURABLE STEEL

REUSABLE

NEW PRODUCT LAUNCH!





NEXT GENERATION FIRE PROTECTION STAND 3A/D10 N